
RECOMMENDED CUTTING CONDITIONS



This list of recommended cutting conditions is for cutters with diameter ≤ \$\phi 80\$. For cutters with diameter greater than \$\phi 80\$ increase cutting speed by around 10%. Above sizes are for OEMX1705.......


Π	Workpiece Material	Hardness	Grade	Cutting Speed (m/min)	Cutting Mode	Feed per Tooth (mm/t)
Р	Mild Steel	≤180HB	F7030	240 (180-300)	A	0.2 (0.15-0.25)
-					В	0.2 (0.15-0.25)
			VP15TF	180 (100—250)	C,E,F	0.2 (0.15-0.25)
					D,G,H,I	0.075 (0.05-0.1)
	Carbon Steel Alloy Steel	180-280HB	F7030	200 (140—240)	A	0.2 (0.15-0.25)
					В	0.2 (0.15-0.25)
			VP15TF	180 (100—250)	C,E,F	0.2 (0.15-0.25)
					D,G,H,I	0.075 (0.05-0.1)
		280—380HB	F7030	150 (100—170)	A	0.2 (0.15-0.25)
					В	0.2 (0.15-0.25)
			VP15TF	120 (80-160)	C,E,F	0.2 (0.15-0.25)
					D,G,H,I	0.075 (0.05-0.1)
	Pre-Hardened Steel	35-45HRC	F7030	130 (90-160)	A	0.15 (0.1-0.2)
					В	0.15 (0.1-0.2)
			VP15TF	120 (80-160)	C,E,F	0.1 (0.05-0.15)
					D,G,H,I	0.05 (0.025-0.075)
	High Alloy Steel	≤300HB	F7030	150 (100—170)	A	0.15 (0.1-0.2)
					В	0.15 (0.1-0.2)
			VP15TF	120 (80-160)	C,E,F	0.1 (0.05-0.15)
					D,G,H,I	0.05 (0.025-0.075)
М	Stainless Steel	≤270HB	F7030	200 (140-240)	A	0.15 (0.1-0.2)
					В	0.15 (0.1-0.2)
			VP15TF	150 (100—200)	C,E,F	0.1 (0.05-0.15)
					D,G,H,I	0.075 (0.05-0.1)

- Revolution (min⁻¹)=(1000 x Cutting Speed)÷(3.14 x DC)
- Table Feed (mm/min)=Feed per Tooth x Number of Teeth x Cutter Revolution
- Note 1) This list of recommended cutting conditions is for flank wear of 0.3mm in 30 min. cutting time.
- Note 2) More than 50mm shank length should be clamped in the milling chuck.
- Note 3) Use step cutting when driling (0.5 mm steps are recommended).
- Note 4) If chatter occurs, adjust the cutting speed.
- Note 5) When using round inserts, make sure that the flat portion of the flank surface is secure against the insert seat wall.

Workpiece Material		Hardness	Grade	Cutting Speed (m/min)	Cutting Mode	Feed per Tooth (mm/t)
K		Tensile Strength ≤350MPa	VP15TF	160 (100—220)	A	0.3 (0.25-0.35)
	Gray Cast Iron				В	0.25 (0.2-0.3)
					C,E,F	0.15 (0.1-0.2)
					D,G,H,I	0.075 (0.05-0.1)
			MB730	1500 (1000—3000)	B (D.O.C 0.1-0.5mm)	0.15 (0.1-0.2)
	Ductile Cast Iron	Tensile Strength 360—500MPa	VP15TF	160 (100—220)	A	0.25 (0.2-0.3)
					В	0.2 (0.15-0.25)
					C,E,F	0.1 (0.05-0.15)
					D,G,H,I	0.05 (0.025-0.075)
	Ductile Cast Iron	Tensile Strength 500-800MPa	VP15TF	140 (90—190)	A	0.25 (0.2-0.3)
					В	0.2 (0.15-0.25)
					C,E,F	0.1 (0.05-0.15)
					D,G,H,I	0.05 (0.025-0.075)
Н	Hardened Steel	45-60HRC	VP15TF	80 (50—100)	A	0.15 (0.1-0.2)
					В	0.15 (0.1-0.2)
					C,E,F	0.1 (0.05-0.12)
					D,G,H,I	0.05 (0.025-0.06)
			MB730	150 (100—200)	B (D.O.C 0.1-0.3mm)	0.15 (0.1-0.2)

- Revolution (min⁻¹)=(1000 x Cutting Speed)÷(3.14 x DC)
- Table Feed (mm/min)=Feed per Tooth x Number of Teeth x Cutter Revolution
- Note 1) This list of recommended cutting conditions is for flank wear of 0.3mm in 30 min. cutting time.
- Note 2) More than 50mm shank length should be clamped in the milling chuck.
- Note 3) Use step cutting when driling (0.5 mm steps are recommended).
- Note 4) If chatter occurs, adjust the cutting speed.
- Note 5) When using round inserts, make sure that the flat portion of the flank surface is secure against the insert seat wall.

APPLICATION



Above sizes are for OEMX1705